

Quality Action Dremel® Micro, model 8050

As part of our ongoing quality-assurance checks and data evaluations, we discovered that individual components of the Dremel 8050 Micro do not satisfy our quality standards.

In rare instances the tool may overheat. Additionally some tools may lose their speed control.

The tools in question were produced between July 2014 and May 2015.

Manufacturing date codes:

407	408	409	410	411	412
501	502	503	504	505	

(other codes are NOT affected)



To have your tool replaced or repaired (free of charge) please contact your local Dremel customer service center 1800 333 8 333.

We sincerely apologize for any inconvenience this may cause.